
## ISSG Newsletter

VOL.4 NO. 7 JULY 1982

## Alpha Micro Announces AlphaCARE<sup>sm</sup>



To complement the introduction of the AM-1000 Desktop Computer and the AM-100/L Central Processing Unit to our product line, Alpha Micro has developed a new and innovative service program - AlphaCARE. Designed to provide customer satisfaction through eliminating problems often associated with excessive turn-around times, AlphaCARE is our answer to a more expeditious and

prompt solution to these problems. Therefore, AlphaCARE will, during the standard 120 day warranty period, attempt to meet a forty-eight hour turnaround for replacement for the AM-1000 and AM-100/L for the domestic customer base. We anticipate expanding our international capabilities to include the AlphaCARE program in the near future.

Not only will this new program include the functions

## ISSG Newsletter Index - Volume 4

SUBJECT	NUMBER	PAGE
ALPHALINK - Uses for the AM-110		4
ALPHAPASCAL - Software Notes	5 AND 12	
ALPHASERV - Network Expands	3	<b>2</b>
ALPHASERV - Network Expands	5	2
AM- 610 - Enchancements	2	8
AM-100/T and AM-120 - Jumpers for Use With AM-620	$\overline{\hat{2}}$	11
AM-1010/1011 - Drive Preventive Maintenance	$\bar{2}$	5
AM-1020/1021 - Installation		6
AM-1041 - Installation	1	6
AM-1050/1051 - Drive Filter Change	a sa sa <mark>z</mark> i sa sa sa	2
AM-1060/1061 - Motor Control Board Enhancement	$\frac{1}{2}$	$\bar{7}$
AM-110 - Uses for AM-110	5	4
AM-300 - Interrupt for 2nd in Winchester Systems	5	4
AM-410,420,610 - Controller Board Modifications	3	11
	4	12
AM-422 - Subsystem Main PCB Modification AM-610 - Enhancements	3	2
AM-610 - Video I/O Level Modification	6	4
AM-621 - General Discussion	4 4 7 7	2
	E	8
AM-621 - Streaming Tape Subsystem Maintenance	5	
AM-700 - When to Use the MPC	5	6
AM-710,700 - Parity Command Error Messages	4	9
AM-720 - 512KB Memory Circuit Board	4	2
AMOS - 4.6A Version Release Notes	6	10
AMOS MONITOR CALL - Generating a Shell Program	6	5
AMTEC - Communication/Information Link to ISSG	3	9
AMTEC - Update	2	1
BOOT PROMS - Reference Guide	1	7
CUSTOMER SERIVCE - Defective Returns	1,	1
CUSTOMER SERVICE - Customer Contact Program	3	2
CUSTOMER SERVICE - Returned Goods Policy	1	1
DEVTBL - Configurations for Winchester Systems	3	6
DOCUMENTATION - Adjusment for DSS-10000-24	6	10
MANUFACTURING - Consolidates Facilities	3	<b>1</b> \
NEWSLETTER - Policy Changes	4	1
NEWSLETTER - Software Notes Consolidation	4	1
PACKAGING - Packaging Technology for Alpha Micro	. 6	1
PATCH - Implementing a Patch	6	11
PATCH - Patch to AM120.MAC	6	Sup.
PATCH - Patch to AM310.MAC	6	Sup.
PATCH - Patch to AX310.MAC	, 6	Sup.
PATCH - Patch to BADBLK.PRG	6	Sup.
PATCH - Patch to COMMON.MAC	6	Sup.
PATCH - Patch to COPY.PRG	6	Sup.
PATCH - Patch to CRT410.PRG	6	Sup.
PATCH - Patch to CRT420.PRG	6	Sup.
PATCH - Patch to DATA.PRG	,: <b>6</b>	Sup.
PATCH - Patch to DSKCPY.PRG	<b>.</b> 6	Sup.
PATCH - Patch to DSKPAK.PRG	`6	Sup.
PATCH - Patch to FIXDVR.PRG	6	Sup.
PATCH - Patch to FMT210.PRG	6	Sup.
PATCH - Patch to MAP.PRG	6	Sup.
PATCH - Patch to RUN.PRG AND RUNSML.PRG	6	Sup.

SUBJECT	NUMBER	PAGE
PATCH - Patch to SERCH.SBR	6	Sup.
PATCH - Patch to SYSTEM.MON	6	12
PATCH - Patch to VUE.PRG	6	14
PATCH - Patch to WRMGEN.PRG	6	Sup.
SOFTWARE - Generaing a Shell Program	6	5
SOFTWARE NOTES - AMOS Version 4.6A Release Notes	6	10
SOFTWARE NOTES - CRT610	5	12
SOFTWARE NOTES - Documentation Adj. DSS-10000-24	6	10
SOFTWARE NOTES - Implementing a Patch	6	11
SOFTWARE NOTES - Placement of QUEUE Command	5	11
SOFTWARE NOTES - Software Hints	5	12
SOFTWARE NOTES - VCR and Streamer Subsystems	5	12
SOFTWARE NOTES - WRMGEN and Alternate Track Tables	5	11
STREAMER AND VCR SUBSYSTEMS - Software Notes	5	12
TRAINING - Schedule for March - September 1982	3	2
TRAINING - Video Training Tapes	5	1
VCR - CRT Options	2	1
VCR - Choosing and Maintaing a VCR	6	2
VCR - Save and Restore Program	4	10
VCR AND STREAMER SUBSYSTEMS - Software Notes	5	12
WINCHESTER SYSTEMS - General Discussion	1	9